

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program April 19, 2011

	DEAN
Reviewed:	AIM

Mine Name: Organa Claims	Permit Number: S/055/0013		
Operator Name: Organa Minerals Products Inc.	Inspection Date: April 19, 2011		
Inspector(s): Sue Fivecoat BLM, Wayne Western DOGM	Time: 10:45 – 11:10 AM		
Other Participants: none	Mine Status: Active		
Other Participants: none	Mine Status: Active		

	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds			
2.	Public Safety (shafts, adits, trash, signs, highwalls)			
3.	Protection of Drainages / Erosion Control			
4.	Deleterious Material			
5.	Roads (maintenance, surfacing, dust control, safety)			
6.	Concurrent Reclamation			
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8.	Water Impoundments			
9.	Soils			
10.	Re-vegetation			
11.	Air Quality			
12.	Other			

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The Operator needs to reclaim the test area on the west side of the road. The Operator did an exploration project on the west side of the road. The BLM said that the Operator was supposed to reclaim the area at the end of 2010. The exploration site is located at an unimproved campsite. Due to multiple uses in the area the BLM wants the Operator to reclaim the area if they will not be mining.

The Operator blazed a new road to the site. See pictures. The site that has been used for production appeared stable.

Fees were paid for 2010.

Conclusions and Recommendations:

The Division should request that the bond be increased and that the Operator reclaim the exploration.

Directions:

Go north on the Factory Butte Road for 8.4 miles from SR 24. The road runs approximately north-northwest. Just before getting to the mine, the road curves to the west and crosses a small culvert. The mine is on the other side of the hills on the north or northeast side. If one passes the mine, the main road crosses a drainage with a 48-inch culvert.

There is no actual road to the mine. It looks as if someone just drove over the hill to get to the site, so, depending on how recently someone has been there, it may or may not be possible to see the access.

and Wester


Inspector's Signature

Sue Fivecoat@blm.gov


WHW

cc: (OPERATOR)

O:\M055-Wayne\S0550013-Organa\inspections\ins-04192011.doc




Exploration operations



Exploration operations west of road in multiple use area.



Access road to eastern operation



Disturbance on east side of road